




AQ Matic Valve & Controls Company, Inc.

March 3, 2020

PERFORMANCE BULLETIN 129

58 Series Stager Motor Update

Due to a supply outage on 12 Volt 58 Series Stager motors PN 1075779, AQ Matic is transitioning to a new motor manufacturer. The new motors have slightly higher torque and are a direct replacement to the current except the new motors do not have a clutch. Because they do not have a clutch, **the new motors cannot be rotated by hand.**



If manual rotation of the stager is required with the new motors shown above, the two motor mounting screws will need to be removed and the motor disengaged from the stager cam.

Thank you for your business.