



February 22, 2018

PERFORMANCE BULLETIN 106

Hycar Disk Replaces Teflon Disk in High Temperature Kits

In 2011, Teflon Disks were replaced with Hycar Disks in all VAV valve assemblies. The Teflon Disks were kept in the High Temperature Repair Kits at that time. A change is underway to fully obsolete the Teflon Disks and replace with Hycar Disks once current inventory is exhausted. This change does not affect the form, fit, or function of the parts and the temperature rating remains unchanged.

A list of the affected kits is below:

Kit PN	Kit Model	Description	Notes
1070498	AV1-RAHT	KIT,AV1,D&S,-FV,-JT	1074144 Replaces 1074145
1070502	AV4-RAHT	KIT,AV4,D&S,-FV,-JT	1074234 Replaces 1074235
1070503	AV5-RAHT	KIT,AV5,D&S,-FV,-JT	1074310 Replaces 1074311
1070510	AV6-RAHT	KIT,AV6,D&S,-FV,-JT	1074392 Replaces 1074393
1070516	AV7-RAHT	KIT,AV7,D&S,-FV,-JT	1074490 Replaces 1074491
1070521	AV8-RAHT	KIT,AV8,D&S,-FV,-JT	1074571 Replaces 1074572

A list of the Teflon Disks that will be obsoleted once inventory depletes is below:

Item PN	Model	Description	Replaced By
1074145	421-JT	DISC,421,TEFLON	1074144 DISC,421,HYCAR
1074235	424-JT	DISC,424,TEFLON	1074234 DISC,424,HYCAR
1074311	425-JT	DISC,425,TEFLON	1074310 DISC,425,HYCAR
1074393	426-JT	DISC,426,TEFLON	1074392 DISC,426,HYCAR
1074491	427-JT	DISC,427,TEFLON	1074490 DISC,427,HYCAR
1074572	428-JT	DISC,428,TEFLON	1074571 DISC,428,HYCAR

If any questions should arise, please contact us at TechSupport@AQ-Matic.com or +1-262-326-0100.

Thank you for your business,

Jeremy Josetti
General Manager