


December 11, 2019

## PERFORMANCE BULLETIN 117

## K521 Shaft Temporary Alternative

The tool used to mold Shaft PN 1075842 used in K521 series plastic valves is experiencing unexpected issues. This has resulted in an outage of Shaft PN 1075842. While the tool is being repaired, we will offer a machined version of this shaft. The machined PVC version is fully interchangeable with the molded version. We are working diligently to get the molded shaft tool.



If any questions should arise, please contact us at <u>TechSupport@AQ-Matic.com</u> or +1-262-326-0100.

Thank you for your business.





Valves & Controls