




AQ Matic Valve & Controls Company, Inc.

December 6, 2019

**PERFORMANCE BULLETIN 119**

**K520 Shaft Temporary Alternative**

The tool used to mold Shaft PN 1077854 used in K520 series plastic valves is experiencing unexpected issues. This has resulted in an outage of Shaft PN 1077854. While the tool is being repaired, we will offer a machined version of this shaft. The machined PVC version is fully interchangeable with the molded version. We are working diligently to get the molded shaft tool operating.



If any questions should arise, please contact us at [TechSupport@AQ-Matic.com](mailto:TechSupport@AQ-Matic.com) or +1-262-326-0100.

Thank you for your business.