



July 14, 2021

**PERFORMANCE BULLETIN 128**

**K52 Series Diaphragm Plate Temporary Change to Stainless Steel**

The Diaphragm Plates on K52 series valves may temporarily change to 303 Stainless Steel material. This is being done due to material shortage of the molded plastic plates. New Part Numbers are being introduced for the individual plates as shown below, but repair kit and valve Part Numbers will remain unchanged. The Stainless Steel plates are fully interchangeable with the plastic plates.

We will convert back to molded plastic Diaphragm Plates as supply allows.

Valve Series	Plastic Upper Diaphragm Plate	Stainless Steel Upper Diaphragm Plate	Plastic Lower Diaphragm Plate	Stainless Steel Lower Diaphragm Plate
K520	1077856	1077856M	1077858	1077858M
K521	43042	43042M	43043	43043M
K524	43041	43041M	1076197	1076197M
K526	43050	43050M	43051	43051M

If for any reason you cannot use valves or kits with Stainless Steel plates please contact our sales department [sales@aq-matic.com](mailto:sales@aq-matic.com) or +1-262-326-0100 for current lead time on the all plastic versions.

Thank you for your business.