



July 28, 2023

PERFORMANCE BULLETIN 137 K531, K534, K535 Retaining Ring Update


The Retaining Rings used on K531, K534, and K535 series valves are being updated from plastic to Stainless Steel. The new Retaining Rings will be fully interchangeable with the old and both fit into the same valve body groove.

The new Retaining Rings are similar to those used on K537 and K526 valves. A flat tipped screw driver is used to remove the Retaining Ring. No tools are required to install the rings. The update will be implemented when inventory of the current version is exhausted.









If any questions should arise, please contact us at <u>TechSupport@AQ-Matic.com</u> or +1-262-326-0100.